Please substitute paragraph [0023], with the following paragraph. A marked-up copy of this paragraph, showing the changes made thereto, is attached.

04

-[0023] As illustrated in Figs. 2 and 4, a face 20 of the connector 16 on top of the mount 1 has one or more holes or slots 18, which receive bayonets 23 located on a mounting surface 24 of the crowning ornament 26 in a bayonet-style coupling. Of course, other alternatives for securing the ornament to the connector can be provided.

Please substitute paragraph [0024], with the following paragraph. A marked-up copy of this paragraph, showing the changes made thereto, is attached.

03

## IN THE CLAIMS:

Please cancel Claims 2, 8 and 11 without prejudice to or disclaimer of the information recited therein. Please amend Claims 1, 6, and 9 as shown below. A marked-up version Claims 1, 6, and 9, showing the changes made thereto, is attached. Please note that all claims currently pending in this application are reproduced below for the Examiner's convenience regardless of whether the claim is being amended.

July 7

1. (Amended) A tree-top mounting device, comprising:

a housing;

an elongated support slidably received within said housing;

a fitting head disposed at a distal end of said elongated support;

a fastener adapted to secure said housing to a tree; and

04